



Customer Support Services PARTS MANUAL Revised 30 Jul 2008


OPERATION MANUAL	M051-00K62-A111
SERVICE MANUAL	M051-00K62-A060
HARDWARE BAG	AK62-00152-0001
Telemetry Kit (Optional)	GK47-00002-0003
PLUG IN OPTION KIT – 120/60	GK62-00002-0018
PLUG IN OPTION KIT – 240/50 UK	GK62-00002-0019
PLUG IN OPTION KIT – 240v AUS	GK62-00002-0020
PLUG IN OPTION KIT - 230/50 CONT	GK62-00002-0021

	Page
CONSOLE SUPPORT & DEADSHAFT COVERS	4
HANDLEBARS AND BULLHORNS	5
CONSOLE AND RELATED COMPONENTS	6
UPPER FRAME HARDWARE	7
ROCKER ARMS AND PEDAL LEVERS	8
CRANK COVER AND LOWER CAPS	9
LOWER FRAME SHROUDS AND HARDWARE	10
PEDAL LEVER COMPONENTS	11
DRIVE MODULE COMPONENTS AND MAIN CABLE	12
DRIVE MODULE HARDWARE	13
CABLES	14
Note: The 90X Telemetry is an option.	






*Right Bullhorn Assembly consists of: AK62-00057-0000 Bullhorn, 0K62-01136-0000 Grip and 0K62-01199-0001 Gasket Left Bullhorn Assembly consists of: AK62-00058-0000 Bullhorn, 0K62-01136-0000 Grip and 0K62-01199-0001 Gasket



CONSOLE	OVERLAY/BEZEL/SWITCH	LANGUAGE
AK62-00151-0001	AK62-00189-0001	Eng + Met
AK62-00151-0003	AK62-00189-0003	Ger/Met
AK62-00151-0004	AK62-00189-0004	Spn/Met
AK62-00151-0006	AK62-00189-0006	Jap/Met
AK62-00151-0007	AK62-00189-0007	Frn/Met
AK62-00151-0008	AK62-00189-0008	Ital/Met
AK62-00151-0009	AK62 <i>-00189-</i> 0009	Dut/Met
AK62-00151-0010	AK62-00189-0010	Port/Met

CROSS-TRAINER 90X Upper Frame Hardware



Items Not Shown:


Accessory Tray	0K62-01022-0000
Mounting Screws (2)	0017-00101-1846


CROSS-TRAINER 90X Rocker Arms & Pedal Levers

Rocker Arms Kit GK62-00002-0070 contents:


Rocker Arms (2)
Hardened Spacers (2)
Oilite Washers (2)
Retaining Rings (2)
Loctite 620
Alcohol pad

Rocker Arms AK62-00002-0070 Shaft Collar w/Screws 0K61-01259-0000






Lower Frame Shrouds & Hardware



CROSS-TRAINER 90X Pedal Lever Assembly Components



Note: If replacing the Tie Rod Assembly or Crank Extension for the first time, order kit GK62-00002-0015. Both sides must be replaced simultaneously in this situation.

Drive Module components & Cable

